

Eyewear Cleaning Guide:

MCR Safety recommends the following specific cleaning instructions when cleaning our glasses, goggles and face shields.



1. First rinse debris and dirt from lens with warm water.
 2. Wash with mild soap.
 3. Rinse clean again with warm water.
 4. Then remove excess water with a soft tissue or microfiber cloth.
 5. If mild soap and water are not present at job site, we also recommend MCR Safety's lens cleaning towelettes (LCT) or spray bottle cleaning solution (LCS1).
- Note: Do not use other competitor cleaning wipes if they contain more than 15% alcohol as this may damage the polycarbonate frames and lenses nor use "autoclave" machines as these will turn the material a yellow tint and cause it to become brittle over time. Please let us know if you are in need of further information. Thanks again for your inquiry and your continued support of our MCR Safety brands.



**MCR
SAFETY**

800-955-6887 | www.mcrcsafety.com